# RECEINED TIME MAR 14. 10:188M ALAL SAFETY DATA SHEET

#### JULY, 1998

### PERMATHERM, INC. 269 INDUSTRIAL PARK ROAD MONTICELLO, GA 31064

#### EMERGENCY TELEPHONE NUMBER

(706-468-7500)

#### SECTION NOMENCLATURE

CHEMICAL NAME......Expanded Polystyrene foam (EPS)
CHEMICAL FAMILY.....Polystyrene
FORMULA......(C<sub>2</sub>H<sub>2</sub>)n with flame

retardant

#### SECTION II HAZARDOUS INGREDIENTS

None when residual pentane blowing agent is reduced to level described in Section 1X.

#### SECTION III PHYSICAL DATA

BOILING POINT......Not Applicable
SOLUBILITY IN WATER....None
DENSITY......0.75 - 2.0 PCF
PERCENT VOLATILE (VOL)..0.18% Pentane &
Water
EVAPORATION RATE.....Not Applicable
APPEARANCE & COLOR....Rigid Cellular Foam
Block or Board, White, No Odor.

#### SECTION IV FIRE AND EXPLOSION

EXTINGUISHING MEDIA.....Water Fog, CO<sub>2</sub>,
Dry Chemical
SPECIAL FIRE FIGHTING PROCEDURES...None
UNUSUAL FIRE & EXPLOSION HAZARDS...May Emit
Large Volumes of Dense, Black Smoke

#### SECTION V HEALTH HAZARD

THRESHOLD LIMIT VALUE......None EFFECTS OF OVEREXPOSURE......None EMERGENCY & FIRST AID PROCEDURES......NONE

#### SECTION VI REACTIVITY DATA

STABLE......YES
INCOMPATIBILITY.....NONE
HAZARDOUS DECOMPOSITION...NONE
CONDITIONS TO AVOID......Do Not
Expose to Flame or Other Ignition Source

#### SECTION VII SPILL OR LEAK

Normal good housekeeping should be observed in properly disposing of scrap material. Dispose of waste in accordance with local ordinances.

## SECTION VII SPECIAL PROTECTION INFORMATION

RESPIRATORY PROTECTION .. NONE
May act as obstruction of swallowed.
VENTILATION.......None
PROTECTIVE GLOVES.....None
EYE PROTECTION......Safety Glasses
recommended to avoid dust if saw is
used for fabrication.

#### SECTION IX SPECIAL PRECAUTIONS

Immediately after molding EPS into blocks the residual blowing agent, pentane, entrapped within the blocks ranges from about 2.0 to 3.0% by weight. The blocks are then stored at room temperature or at elevated temperatures (e.g. < 150° F.) to reduce the entrapped pentane and moisture to less than 1% by weight (0.18% by volume) for dimensional stabilization. The block storage areas must be adequately ventilated to avoid a hazardous build-up of flammable pentane vapors. If the product in block or board form is to be fabricated by hot-wire cutting, work areas should be ventilated to avoid a buildup of processing fumes.